MATERIAL SAFETY DATA SHEET

IDENTIFY: DURALINE D-330

DATE PREPARED:

Jan 2010

COMPANY NAME and ADDRESS

Duraline LLC

5901 Baptist Road

Pittsburgh PA 15236

EMERGENCY PHONE

803 285 4831

INFORMAL PHONE NUMBER

412 831 9200

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Hazardous			Other Limits	
Components	OSHA PEL	ACGIH TLV	Recommended	%
None	-	_	***	

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point		Specific Gravity (H2O = 1)	
	230 °F		1.28
Vapor Pressure (mm Hg.)		Melting Point	/
	12 mmHg @ 70 °F		N/A
Vapor Density (AIR = 1)	2	Evaporation Rate (Butyl Acetate = 1)	
	N/A		N/A
Solubility in Water			
Highly soluble.			
Appearance and Odor		<u> </u>	
Black with slight odor.			

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Flash Point (Method Used) None	Flammable Limits N/A	LEL N/A	UEL N/A
Extinguishing Media N/A			
Special Fire Fighting Procedures N/A	,		
Unusual Fire and Explosion Hazards N/A			4

SECTION V - REACTIVITY DATA

Stability	Unstable		Conditions to Avoid
		No	None
	Stable	Yes	i No
		res	
Incompatibility (Materials to Avoid)			
Do not use aluminum in undiluted cor	ncentrates.		
Hazardous Decomposition or Byproducts			
None			
Hazardous Polymerization	May Occur		
		No	Conditions to Avoid
	Will Not Occur		
		Yes	None

SECTION VI - HEALTH HAZARD DATA

Route(s) of Entry	Inhalation?	Skin?	Ingestion	?
	No	Yes		Yes
Health Hazards (Acu	ute and Chronic)			8
Direct contact v	vith concentrate (ui	ndiluted) may cause sk	in dryness. May	cause discomfort if exposed to
cuts or abrasion	ns.			
Carcinogenicity	NTP?	IARC Monographs?	OSHA Regula	ated?
	[*] No	No	Table 1975 Act 1975 A	No
Signs and Symptom	s of Exposure			
Dryness of skin	and burning on op	en cuts and abrasions.	3	
Medical Conditions	Generally Aggravat	ed by Exposure		
None				~
Emergency and Firs	t Aid Procedures			
Wash immediate	ely and flush eyes in	mmediately. If irritation	n persists, conta	ct a physician.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to Be Taken in Case Material Is Released or Spilled	
Sweep with absorbent type floor sweep.	
Waste Disposal Method	
Dispose of as common waste.	1
Precautions to Be Taken in Handling and Storing	
None	· ·
Other Precautions	
None	

SECTION VIII - CONTROL MEASURES

P 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Respiratory Protection (Specify Ty	/pe)	
None		
Ventilation	Local Exhaust	Special
	None	None
	Mechanical (General)	Other
	None	None
Protective Gloves	Eye Protection	
Optional	None	
Other Protective Clothing or Equi	pment	
None		
Work/Hygienic Practices		
N/A		·